25X1X PLACE OBTAINED DATE OF CONTEI DATE OBTAINED REFERENCES PAGES 25X1C 25X1C 25X1C 26 January 1953 PAGES 2 ENCLOSURES (No. & TYPE) 3 - three documents REMARKS	at de Maria de La Louis sport Maria de Maria de La
DATE OBTAINED. EFERENCES AGES 25X1C RED 26 January 1953 AGES 2 ENCLOSURES (No. & TYPE) 3 - three documents	er eta kalundensa massada ka
ATE OBTAINED_ 25X1C RED_ 26 January 1953 EFERENCES AGES2 ENCLOSURES (No. & TYPE)3 - three documents	7 AT 100 SAU RE25(1)
AGES 2 ENCLOSURES (No. & TYPE) 3 - three documents	
EMARKS	Name of the last o
The company of the co	i-destro manerale
	THE PERSON NAMED OF THE PE

SOURCE

25X1X

- 1. Motor vehicles turned in at the central vehicle repair shop in Berlin-Oberschoeneweide for repair or overhaul from 20 October through 18 November included: 10 Willysjeeps, 2 old buses, 47 chassis for repair shop trucks, 227 engines including 93 ZIS, 32 Chevrolets, 43 Studebakes, 13 Fords, 9 Willys, and 37 GAZ engines. All this equipment arrived from Zeesen. Forty-eight ZIS engines arrived by rail from Ketschondorf. Not all of the incoming equipment was observed by source.
- 2. Vehicles observed leaving the installation during the same period included:
 - a. To Zeesen:

Mine Willys jeeps, 2 buses, 40 repair shop trucks, 251 engines including 106 ZIS, 38 Chevrolets, 24 Studebakers, 31 Fords, 33 Willys, and 19 GAZ engines.

- b. Three repair shop truck bodies were sent to in Finow and 680 new motor blocks including 590 for ZIS engines, 280 for Ford engines, and 20 for Willi engines were sent to Ketschendorf.
- 3. Three hundred ZIS engine motor blocks and 450 Studebaker motor blocks were to be prepared for installation at the vehicle repair plant in November 1952.

25X1A 1

25X1A

Comment. This is the first time that the number of Soviet engines turned in at the installation for repair exceeded the number of U.S.-made engines.

It is believed that this situation is due to the vehicle replacement program during which over-age lend-lease vehicles were descrivated.

The report indicates that the number of damaged engines sent to the vehicle repair shop decreased considerably as compared with the number of engines turned in during the preceding months.

25X1A

CLASSIFICATION SECRET/CENTROL - U.S. OFFICIALS ONLY



25X1A

25X1C

25X1A

Comment.

a vehicle repair shop in

SECRET/CONTROL - U.S. OFFICIALS ONLY